

Sulzer RTA58 Cylinder Cover Recondition.

Write and Ask – brovertek@gmail.com

Company profile: <http://brovertek.com/13001>

Price EURO 3865 (the price for custom documents export & transit documents export are included).

"O" ring grooves is rebuilt and machined. Seating surface for valve seat is full reconditioned. Cyl. cover is high Pressure Tested, cleaned & painted.

Burgas (EU Bulgaria) Stock.



